

Fig. 1

Base Station of Interest
or MCU Generates
Measurement Request

S10

Fig. 2

MCU Routes Request
to Identified BSs

S15

Identified BSs Send
Measurement Instructions
to Mobile Terminals

S20

Mobile Terminals Make
Measurements

S25

Receive Results at Identified BSs

S30

SEND to MCU

S35

SEND to Base Station of Interest

S40

0050087-01500




Fig. 3




Fig. 4




Fig. 5

00260997 004600 00260997 004600

Base Station of Interest
or MCU Generates
Measurement Request

S10

Fig. 6

MCU Routes Request
to Identified BSs

S15

Identified Base
Stations Make
Measurements

S120

SEND to MCU

S35

SEND to Base Station of Interest

S40

609720 2805260